

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



Project Name Villa's at Gardner Road	Date 6-26-18
Location Lynhurst Ave. Village of Horseheads	Permit # NYR11A108
Weather Conditions Sunny, warm	Entry Time: 9:00
On-Site Representative Present: John Mackinster-Bomack	Exit Time: 9:40

Construction Site Notes:

	-Most of site grading for Phase 1 has been completed.
	-Working on installing storm sewers and drainage at this time.

Yes	No	N/A	
X			All erosion and sediment control measures installed/constructed
X			All erosion and sediment control measures maintained properly
		X	Are there currently more than 5 acres disturbed w/o prior approval
X			Have stabilization measures been initiated in inactive areas
X			Are permanent stormwater control measures being implemented
	X		Was there a discharge into the receiving water on the day of inspection
	X		Evidence of turbidity or oil in the receiving waters
X			Are weekly inspections being performed?
X			Are the inspections being performed by a qualified individual?

Corrections Needed:

-Construction entrance will need maintenance soon.

Satisfactory	X	Marginal	Unsatisfactory
Date 6-26-18	Inspector <i>Joanna Verigni</i>		



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT: Villa's at Gardner Road
Village of Horseheads
Municipal Construction Inspection
June 26, 2018

BY: Jessica Verrigni, CPESC, CPSWQ



Slopes on west end of phase 1 have been properly stabilized.



Turf Reinforcement Mat (TRM) on site for swale on north end of property.



Stormwater forebay and retention basin.



Swale inlet and storm sewer inlet on south side of forebay.



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT: Villa's at Gardner Road
Village of Horseheads
Municipal Construction Inspection
June 26, 2018

BY: Jessica Verrigni, CPESC, CPSWQ



Emergency Spillway in stormwater retention basin.



Swale along south end of Phase 1 is growing grass and been stabilized.



Construction entrance may need maintenance soon.

