

**Chemung County Stormwater  
Construction Inspection  
Erosion and Sediment Control**



<b>Project Name</b> Six67 Apartments	<b>Date</b> 8/13/2021
<b>Location</b> W. Fifth and College Ave. City of Elmira	<b>Permit #</b> NYR11G564
<b>Weather Conditions</b> sunny, warm	<b>Entry Time:</b> 8:55 am
<b>On-Site Representative Present:</b> none	<b>Exit Time:</b> 9:27 am

Construction Site Notes:	
	-Building is complete on the outside.
	-Final landscaping is happening now.

Yes	No	N/A		
X			All erosion and sediment control measures installed/constructed	
X			All erosion and sediment control measures maintained properly	
	X		Are there currently more than 5 acres disturbed w/o prior approval	
X			Have stabilization measures been initiated in inactive areas	
X			Are permanent stormwater control measures being implemented	
	X		Was there a discharge into the receiving water on the day of inspection	
	X		Evidence of turbidity or oil in the receiving waters	
X			Are weekly inspections being performed?	
X			Are the inspections being performed by a qualified individual?	

Corrections Needed:	
-Areas that had been seeded and mulched along W. Fifth St. had been driven through and have had to be re-seeded and re-mulched. Awaiting 80% vegetation.	
-Filter fabric was left under the grates around the building (between sidewalk and building) preventing water from getting in as intended. Landscaper will remove.	
-Small areas along Columbia Street and College Ave. need stabilization.	

Satisfactory	X	Marginal	Unsatisfactory
<b>Date</b> 8/13/21	<b>Inspector</b> <i>Jessica Verrigni</i>		



COUNTY OF CHEMUNG  
Chemung County Stormwater Coalition  
851 Chemung Street  
Horseheads, New York 14845  
Ph. 607.796.2216

**PROJECT:** Six67 Apartments  
City of Elmira  
Municipal Construction Inspection  
August 13, 2021


**BY:** Jessica Verrigni, CPESC, CPSWQ



Area along Columbia Street requires stabilization.



Area along Fifth Street that has been re-stabilized.



Area along College Ave needing stabilization.



Drainage Grates between the building and the sidewalk need to have the fabric removed from under the grate.