

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



Project Name Hilliard Building Expansion	Date 6-8-2020
Location W. Clinton Street Elmira (City), NY	Permit # NYR11F218
Weather Conditions sunny, warm	Entry Time: 9:53 am
On-Site Representative Present:	Exit Time: 10:00 am

Construction Site Notes:			
-Building construction is completed.			
-Some landscaping has been completed.			
-Erosion on the side slopes of the rain garden have been repaired.			

Yes	No	N/A		
X			All erosion and sediment control measures installed/constructed	
		X	All erosion and sediment control measures maintained properly	
	X		Are there currently more than 5 acres disturbed w/o prior approval	
X	X		Have stabilization measures been initiated in inactive areas	
X			Are permanent stormwater control measures being implemented	
	X		Was there a discharge into the receiving water on the day of inspection	
	X		Evidence of turbidity or oil in the receiving waters	
X			Are weekly inspections being performed?	
X			Are the inspections being performed by a qualified individual?	

Corrections Needed:			
-The area next to the building and above the underground infiltration system has not yet been stabilized. This area has been sitting idle for many weeks.			
Topsoil has been stockpiled on the area above the underground system. One of the observation ports has been knocked crooked and requires repair.			

Satisfactory	Marginal	x	Unsatisfactory
Date 6-8-20	Inspector <i>Jessica Uerrigie</i>		



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT:	Hilliard Building Expansion Project City of Elmira Municipal Inspection June 8, 2020
BY:	Jessica Verrigni, CPESC, CPSWQ



Topsoil was stockpiled on top of underground infiltration and one of the observation ports has been hit by equipment.



Topsoil was stockpiled on top of underground infiltration and one of the observation ports has been hit by equipment.



Future green area next to building and above the underground infiltration has not been stabilized.



Rain Garden- repairs have been made to eroded areas but landscaping is not completed.