

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



Project Name LECOM	Date 8-26-2019
Location Park Place Elmira (City), NY	Permit # NYR11E617
Weather Conditions sunny, cool	Entry Time: 11:53 am
On-Site Representative Present: none	Exit Time: 12:04 pm

Construction Site Notes:

-No earthwork at this time.

Yes	No	N/A		
X			All erosion and sediment control measures installed/constructed	
	x		All erosion and sediment control measures maintained properly	
	X		Are there currently more than 5 acres disturbed w/o prior approval	
		x	Have stabilization measures been initiated in inactive areas	
X			Are permanent stormwater control measures being implemented	
	X		Was there a discharge into the receiving water on the day of inspection	
	X		Evidence of turbidity or oil in the receiving waters	See note
X			Are weekly inspections being performed?	
x			Are the inspections being performed by a qualified individual?	

Corrections Needed:

- CB-2- drop inlet protection is not installed correctly and there is an insert that requires maintenance. **This item has been mentioned multiple times on both the municipal and weekly inspection reports.**
- Sediment is getting onto both Clinton Street and W. Fourth Street. Areas along the curb line should be swept and the sediment disposed of properly. **Noted multiple times.**
- Silt fence along Clinton Street has holes in it and requires replacement.

Satisfactory	Marginal	Unsatisfactory X*
Date 8/26/19	Inspector <i>Jessica Veragini</i>	

*Because items have been noted multiple times with no correction site is considered unsatisfactory.



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT:	LECOM
	City of Elmira
	Municipal Inspection
	August 26, 2019
BY:	Jessica Verrigni, CPESC, CPSWQ



Construction entrance in fair condition although sediment from project site is tracked up Clinton Street and W. Fourth Street.



Drop inlet protection around CB-2 remains installed incorrectly.



Silt fence along Clinton Street has holes and is in need of repair.



Silt fence along Clinton Street has holes and is in need of repair.