

**Construction Inspection  
Erosion and Sediment Control**



<b>Project Name</b> CDS Monarch Senior Living Facility	<b>Date</b> 4-3-19
<b>Location</b> Maple Ave. City of Elmira	<b>Permit #</b> NYR11C547
<b>Weather Conditions</b> Sunny- windy	<b>Entry Time:</b> 1:49 pm
<b>On-Site Representative Present:</b> None	<b>Exit Time:</b> 1:59 pm

Construction Site Notes:

-Work is completed on this project except for finishing up the stormwater basin and some minor grading.

Yes	No	N/A	
<input checked="" type="checkbox"/>			All erosion and sediment control measures installed/constructed
	<input checked="" type="checkbox"/>		All erosion and sediment control measures maintained properly
	<input checked="" type="checkbox"/>		Are there currently more than 5 acres disturbed w/o prior approval
<input checked="" type="checkbox"/>			Have stabilization measures been initiated in inactive areas
<input checked="" type="checkbox"/>			Are permanent stormwater control measures being implemented
	<input checked="" type="checkbox"/>		Was there a discharge into the receiving water on the day of inspection
	<input checked="" type="checkbox"/>		Evidence of turbidity or oil in the receiving waters
<input checked="" type="checkbox"/>			Are weekly inspections being performed?
<input checked="" type="checkbox"/>			Are the inspections being performed by a qualified individual?

Corrections Needed:

-Surface runoff from parking area is still causing major erosion. This erosion is under the blanket in some areas.
-Check dams are not installed correctly.
-Surface runoff from sidewalks at the rear of the building are causing erosion down to the catch basins.

Satisfactory                      Marginal    X                      Unsatisfactory

<b>Date</b> 4-3-19	<b>Inspector</b> <i>Joanna Verigin</i>
--------------------	--



**COUNTY OF CHEMUNG**  
**Chemung County Stormwater Coalition**  
851 Chemung Street  
Horseheads, New York 14825  
Ph. 607.796.2216

**PROJECT:** CDS Monarch Senior Living Facility  
City of Elmira  
Municipal Inspection  
April 3, 2019

**BY:** Jessica Verrigni, CPESC, CPSWQ



Surface runoff from parking is causing erosion down slope of stormwater basin.



Erosion that has occurred. Check dam has not been installed correctly.



Erosion started from runoff over sidewalk to catch basin.

