

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



Project Name Hickory Grove Road Solar Projects	Date 9-24-20
Location Hickory Grove Road Horseheads, NY	Permit # NYR111F809
Weather Conditions sunny	Entry Time: 12:44 pm
On-Site Representative Present:	Exit Time: 1:14 pm

Construction Site Notes:	
	-Work continues to progress on the solar project. Site is actively installing the panel supports.
	-Flow diffusers are being installed where they were proposed in the SWPPP

Yes	No	N/A		
X			All erosion and sediment control measures installed/constructed	
X			All erosion and sediment control measures maintained properly	See Note
	X		Are there currently more than 5 acres disturbed w/o prior approval	
X			Have stabilization measures been initiated in inactive areas	
	X		Are permanent stormwater control measures being implemented	
	X		Was there a discharge into the receiving water on the day of inspection	
	X		Evidence of turbidity or oil in the receiving waters	
X			Are weekly inspections being performed?	
X			Are the inspections being performed by a qualified individual?	

Corrections Needed:	
	-Construction entrance requires maintenance from dust accumulation.
	-Dust is a major concern at this time. Need to incorporate dust control practices.

Satisfactory Marginal X Unsatisfactory

Date 9/24/20 Inspector Jessica Verrigno



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT: Hickory Grove Solar Farm
Town of Horseheads
MS4 Construction Inspection
September 24, 2020

BY: Jessica Verrigni, CPESC, CPSWQ



Construction entrance requires maintenance due to dust accumulation.



Flow diverters are being installed where they are planned.



Dust is a major concern.

