

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



Project Name Hickory Grove Solar Project	Date 4-27-21
Location Hickory Grove Road Horseheads, NY	Permit # NYR11F809
Weather Conditions sunny	Entry Time: 1:43 pm
On-Site Representative Present: Zack Gillespie, APA	Exit Time:

Construction Site Notes:	
	-Active construction is not occurring but restoration has not happened.

Yes	No	N/A		
x			All erosion and sediment control measures installed/constructed	
			All erosion and sediment control measures maintained properly	
	x		Are there currently more than 5 acres disturbed w/o prior approval	
	x		Have stabilization measures been initiated in inactive areas	
	x		Are permanent stormwater control measures being implemented	
	x		Was there a discharge into the receiving water on the day of inspection	
	x		Evidence of turbidity or oil in the receiving waters	
	?		Are weekly inspections being performed?	
			Are the inspections being performed by a qualified individual?	

Corrections Needed:
-Restoration and decompaction has not occurred at this site. There is minimal grass growing and a major water ponding issue on the north end of the project.
-This site is not stabilized so qualified inspections are supposed to be still occurring. I have not seen a weekly inspection since October 13 th , 2020.

Satisfactory	Marginal	Unsatisfactory	X
Date 4/27/21	Inspector <i>Jessica Verrigni</i>		



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216


PROJECT: Hickory Grove Road Solar
Town of Horseheads
Municipal Construction Inspection
April 27, 2021

BY: Jessica Verrigni, CPESC, CPSWQ



Severe compaction with no stabilization.

Open idle areas were left unstabilized all winter.



Standing water issue.



Severe compaction and standing water issue.