

**Chemung County Stormwater  
Construction Inspection  
Erosion and Sediment Control**




<b>Project Name</b> Hickory Grove Solar Farm	<b>Date</b> 8/3/2022
<b>Location</b> Hickory Grove Road Horseheads, NY	<b>Permit #</b> NYR11F809
<b>Weather Conditions</b> sunny	<b>Entry Time:</b> 1:03 pm
<b>On-Site Representative Present:</b> None	<b>Exit Time:</b> 1:27 pm

Construction Site Notes:	
	-Gate code has changed. Could only access site by walking around fenced areas.

Yes	No	N/A		
		x	All erosion and sediment control measures installed/constructed	
			All erosion and sediment control measures maintained properly	
	X		Are there currently more than 5 acres disturbed w/o prior approval	
X	X		Have stabilization measures been initiated in inactive areas	
		X	Are permanent stormwater control measures being implemented	
	X		Was there a discharge into the receiving water on the day of inspection	
	X		Evidence of turbidity or oil in the receiving waters	
?			Are weekly inspections being performed?	
			Are the inspections being performed by a qualified individual?	

Corrections Needed:	
-Parking/Staging area from construction has been mulched. This area was not decompacted. The penetrometer would not go 1" into the ground. Decompaction was required for this entire site.	
-Drive areas within the fenced area do not appear to have been restored. Still look compacted.	
-Areas where topsoil was put down there is no seed and mulch.	
-Could not get to the area where dewatering was to occur. Inaccessible.	

Satisfactory	Marginal	x	Unsatisfactory
<b>Date</b> 8/3/22	<b>Inspector</b> <i>Jessica Verrogiu</i>		




**COUNTY OF CHEMUNG**  
**Chemung County Stormwater Coalition**  
851 Chemung Street  
Horseheads, New York 14825  
Ph. 607.796.2216

**PROJECT:** Hickory Solar Farm  
Town of Horseheads  
Municipal Inspection  
August 3, 2022

**BY:** Jessica Verrigni, CPESC, CPSWQ



Parking/staging areas appear to be restored however are still compact.



Areas driven on during construction do not appear restored.



Areas restored have not been stabilized inside of the fence.



Contractor stockpile yard does not have the excessive mulch removed.