





COUNTY OF CHEMUNG  
Chemung County Stormwater Coalition  
851 Chemung Street  
Horseheads, New York 14825  
Ph. 607.796.2216

**PROJECT:** Souther Tier Logistics  
Village of Horseheads  
Municipal Inspection  
June 29, 2022

**BY:** Jessica Verrigni, CPESC, CPSWQ



Concrete washout not being used.



Silt fence installed incorrectly.




Concrete washout doesn't have liner. The other one has a liner but it isn't held in place correctly.



Silt sock is supposed to be along the entire east side of building. None is in place.

**WATER COALITION**

site for use by the  
Water Management



**NOTES:**

1. FILTER SOCK MATERIAL SHALL BE A HIGH-FLOW, HIGH-STRENGTH, UV-RESISTANT MULTI-FILAMENT POLYESTER KNIT TEXTILE.
2. 8" FILTER SOCK TO BE FILLED WITH A 50-50 MIX OF DUST-FREE LIMESTONE GRAVEL AND COMPOSTED HARDWOOD CHIPS. THE GRAVEL SHALL BE LESS THAN 1 1/2" IN DIAMETER.

*Where do you get this product if it exists?*

**INLET PROTECTION IN PAVEMENT**

6  
C503

N.T.S.

*Work w/ consultant to find product or pick something more appropriate*