



851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT:	Village Hotel
	Village of Horseheads
	MS4 Construction Inspection
	December 22, 2014
BY	Jessica Verrigni, CPESC, CPSWQ



Correction made to each gap in the silt fence.



Drop inlet protection-stone placement is good but the wrong fabric material was used. Water will not flow through this.



Stormwater basin rough graded.



Silt fence and disturbed area along I-86 West.

