

Website Updated:
 Active Construction List
 Updated:

Chemung County Stormwater
 Construction Inspection
 Erosion and Sediment Control



Project Name		Best Western/Village Hotel		Date	1-25-16
Location		SR 14 Horseheads		Permit #	NYR10Y122
Weather Conditions		Overcast, cold		Entry Time:	10:30
On-Site Representative Present:		Tom Shen (owner), Bob Young (Village)		Exit Time:	10:56
Construction Site Notes:					
-Building footprint complete.					
-Storm sewer system complete.					
Yes	No	N/A			
	X		All erosion and sediment control measures installed/constructed		
	X		All erosion and sediment control measures maintained properly		
	X		Are there currently more than 5 acres disturbed w/o prior approval		
	X		Have stabilization measures been initiated in inactive areas		
X			Are permanent stormwater control measures being implemented		
	X		Was there a discharge into the receiving water on the day of inspection		
	X		Evidence of turbidity or oil in the receiving waters		
X			Are weekly inspections being performed?		
X			Are the inspections being performed by a qualified individual?		
Corrections Needed:					
-Drop inlet protection has not been installed on any catch basin.					
-Concrete washout will need to be maintained/replaced by the next concrete pour.					
-Stormwater pond appears to be overexcavated.					
-Stabilization of all open soil is required.					
-Approved swppp needs to be followed.					
Satisfactory		Marginal		Unsatisfactory X	
Date	1/25/16	Inspector	Jessica Verrigni		



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT: Horseheads Hotel
Village of Horseheads
Municipal inspection
January 25, 2016

BY: Jessica Verrigni, CPESC, CPSWQ



Concrete washout requires maintenance before the next scheduled concrete pour.



Soil exposed and not stabilized. Drop inlet protection not installed at any of the catch basins.



Stormwater basin appears to be over excavated.

