

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



Project Name Six67 Apartments	Date 8-11-2020
Location College Ave Elmira, NY	Permit # NYR11G564
Weather Conditions sunny, humid	Entry Time: 8:11 am
On-Site Representative Present:	Exit Time: 8:24 am

Construction Site Notes:			
-Building is under construction.			

Yes	No	N/A	
<input checked="" type="checkbox"/>			All erosion and sediment control measures installed/constructed
	<input checked="" type="checkbox"/>		All erosion and sediment control measures maintained properly
	<input checked="" type="checkbox"/>		Are there currently more than 5 acres disturbed w/o prior approval
		<input checked="" type="checkbox"/>	Have stabilization measures been initiated in inactive areas
<input checked="" type="checkbox"/>			Are permanent stormwater control measures being implemented
	<input checked="" type="checkbox"/>		Was there a discharge into the receiving water on the day of inspection
	<input checked="" type="checkbox"/>		Evidence of turbidity or oil in the receiving waters
<input checked="" type="checkbox"/>			Are weekly inspections being performed?
<input checked="" type="checkbox"/>			Are the inspections being performed by a qualified individual?

Corrections Needed:			
-Silt fence around the site needs maintenance. There are holes present, its knocked down and building materials are being placed on top of it.			
-Concrete trucks are not getting the washed material into the pit and others aren't even using the pit.			

Satisfactory Marginal X Unsatisfactory

Date 8/11/20	Inspector <i>Jessica Verrigni</i>
---------------------	--



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT: Six67 Apartments
City of Elmira
Municipal Construction Inspection
August 11, 2020

BY: Jessica Verrigni, CPESC, CPSWQ



Not all concrete trucks are using the washout or getting it into the washout pit.

Not all concrete trucks are using the washout or getting it into the washout pit.



Silt fence is requires maintenance. It is down in some areas, encroached on in others and the building panels are on top of it in other locations.



Silt fence has holes in it. It is being encroached upon with traffic around the building.