

Chemung County Department of Health
Environmental Health Services
103 Washington Street P. O. Box 588, Elmira, NY 14902-0588
(607) 737 - 2019
EHS@co.chemung.ny.us

Institutional Food Service Inspection -- Summary Report

Operation: DIVEN SCHOOL CAFETERIA (ID: 265526)
Facility Name: DIVEN SCHOOL
Facility Code: 00380-09 Facility Email: None
Facility Address: 1115 HALL STREET ELMIRA, NY 14901

To the Attention of:
KARI CROUSE ELMIRA CITY SCHOOL DISTRICT
C/O - ELMIRA H.S. (Attn: K. CROUSE) 777 S. MAIN ST.
ELMIRA , NY 14904- Owner/Operator Email: kcrouse@gstboces.org

Field Visit

Date: APR 10, 2017 01:08 PM
Inspector: Michael Cain (mcain@co.chemung.ny.us)
Responsible Person: Copy of report was sent via e-mail to Mike Dunn, Maintenance Super. and Keri Crouse on 4-10-17.
(email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected: 0
Number of other violations found: 1

Each item found in violation is reported below along with the code requirement.

IMPROPER SANITARY FACILITIES AND CONTROLS.

ITEM # 12C WAS FOUND IN VIOLATION 1 TIME(S).

All or parts of the violation item are IN violation.

Code Requirements

Plumbing and sinks not properly sized, installed, maintained; equipment and floors not properly drained

Inspector Findings

Made field visit to recheck hot and cold water temperatures at kitchen sink taps. Met at facility with district maintenance staff, school was not in session today (vacation). At 1:30 PM, checked cold water tap at kitchen 3-bay sink. Temperature was initially in low 70 degree F but jumped up to low 80's within 1 minute. Cold water was running for over 5 minutes and temperature fell back to 72-73 degrees F. Also checked cold water at larger sink along west wall (toward Wegman's). Had similar temperature results for cold water, hot water was also checked and stabilized at 122 degrees F after 2 minutes running. Then proceeded to shut-off hot and turned cold water tap back on- water temperature was initially around 68 degrees F, then increased into the mid 70's before dropping back to low 60's after 2 minutes. Also checked cold water at single-bay center island sink and cold water dropped to mid-50's after running for 2 minutes.

Additional Information Collected During Inspection

Comments

Was accompanied by Bob McCarick, Maintenance Dept. during field visit.

END of REPORT

[Submit# 278771] DIVEN SCHOOL CAFETERIA (ID 265526) Inspection# 1001956800