

Chemung County Department of Health
Environmental Health Services
103 Washington Street P. O. Box 588, Elmira, NY 14902-0588
(607) 737 - 2019
EHS@co.chemung.ny.us

Food Service Establishment Inspection -- Summary Report

Operation: ARBY'S #6527 (ID: 985378)
Facility Name: ARBY'S #6527
Facility Code: 00173-01 Facility Email: None
Facility Address: 2487 CORNING ROAD ELMIRA, NY 14903

To the Attention of:
CHRISTIAN STARKS ARBY'S RESTAURANT GROUP, INC.
ATTN: PERMITS/LICENSES 1155 PERIMETER CENTER WEST
ATLANTA , GA 30338- Owner/Operator Email: tkoch@arbys.com

Pre-op Inspection
Date: MAR 06, 2018 10:19 AM
Inspector: Erin Walmsley (ewalmsley@co.chemung.ny.us)
Responsible Person: Sandy Parker
(email: gadarbys6527@gmail.com)

Summary
Number of public health hazards found: 0
Number of public health hazards NOT corrected: 0
Number of other violations found: 3

Each item found in violation is reported below along with the code requirement.

POOR SANITARY DESIGN, CONSTRUCTION, INSTALLATION OF EQUIPMENT AND UTENSILS.

ITEM # 10B WAS FOUND IN VIOLATION 1 TIME(S).

All or parts of the violation item are IN violation.

Code Requirements

Non-food contact surfaces and equipment are improperly designed, constructed, installed, maintained (equipment not readily accessible for cleaning, surface not smooth finish)

Inspector Findings

Door gasket lacking on slicer/back line side of alto-shaam. Manager called and part being delivered today (3/6/18). Facility will have to call and schedule maintenance to install.

IMPROPER CONSTRUCTION AND MAINTENANCE OF PHYSICAL FACILITIES.

ITEM # 15A WAS FOUND IN VIOLATION 2 TIME(S).

All or parts of the violation item are IN violation.

Code Requirements

Floors, walls, ceilings, not smooth, properly constructed, in disrepair, dirty surfaces

Inspector Findings

1) Observed expanding foam filling hole in wall next to hand wash sink opposite of mop sink. Discussed requirement for surfaces to be smooth and easily cleanable. Manager has repair being done today. 2) Discussed leaking water from ceiling tiles above back line, roast beef slicer and 3 bay sink area. Manager stated she was told by contractor that when it rains or snow melts water comes into vents system through cracks in AC unit on roof of building. Contractor is scheduled to start repairs within next day or 2 but that start time might be pushed back with forecasted weather conditions. Manager will put up plastic over ceiling as a temporary repair until permanent fix. Manager to email pictures of plastic up to CCHD.

Additional Information Collected During Inspection

Comments

Time table of correction for all items established for 3/20/18. Manager stated that existing hot and cold holding waivers for sliced roast beef and cheeses will continue to be followed in the same manner as under previous ownership.

END of REPORT

[Submit# 368575] ARBY'S #6527 (ID 985378) Inspection# 1002278934