Website Updated: ☐
Active Construction List Updated ☑

Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control

Project Name Fairport Ridge	Date 8-29-17
Location Prospect Hill Horseheads NY	Permit #NYR11B687
Weather Conditions cool, overcast	Entry Time: 10:40
On-Site Representative Present: Scott Moss-owner	Exit Time: 11:15

Construction Site Notes:

-currently grading site around building 7, 2, and 3. Building 7 basement walls are in.
-soil stockpile is actively being worked. When finished stockpiling will install silt fence.
-concrete washout - contractor is having trucks washout into basement of building 7 because he needs the fill. He asked if this was acceptable and I told him yes because it is contained. He will install regular concrete washout when fill is not needed.

Yes	No	N/A		
X			All erosion and sediment control measures installed/constructed	
X			All erosion and sediment control measures maintained properly	
	X		Are there currently more than 5 acres disturbed w/o prior approval	
		X	Have stabilization measures been initiated in inactive areas	
X			Are permanent stormwater control measures being implemented	
	X		Was there a discharge into the receiving water on the day of inspection	
	X		Evidence of turbidity or oil in the receiving waters	
X			Are weekly inspections being performed?	
X			Are the inspections being performed by a qualified individual?	

Corrections Needed:

Satisfactory X Marginal Unsatisfactory

Date 8/29/17 Inspector Jessica Verrigni

COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT:	Fairport Ridge Town of Horseheads Municipal Inspection August 29, 2017
BY:	Jessica Verrigni, CPESC, CPSWQ



Construction entrance installed.

Topsoil stockpiles.

Silt fence installed.

Concrete trucks are washing into basement of Building 7.