



Project Name	Best Western/Village Hotel	Date	5-13-16
Location	SR Horseheads	Permit #	NYR10Y122
Weather Conditions	overcast, raining	Entry Time:	10:40
On-Site Representative Present:	Tom Sownrr3	Exit Time:	11:10

Construction Site Notes:

-no site work grading occurring at this time.
-working on elevator shaft.

Yes	No	N/A	
	✓		All erosion and sediment control measures installed/constructed
	✓		All erosion and sediment control measures maintained properly
	✓		Are there currently more than 5 acres disturbed w/o prior approval
	✓		Have stabilization measures been initiated in inactive areas
		✓	Are permanent stormwater control measures being implemented
	✓		Was there a discharge into the receiving water on the day of inspection
	✓		Evidence of turbidity or oil in the receiving waters
✓			Are weekly inspections being performed?
✓			Are the inspections being performed by a qualified individual?

Corrections Needed:

-silt fence requires replacement. Too far gone to maintain.
-catch basin protection needs to be instlled.
-concrete washout needs replacement.

Satisfactory	Marginal	<input checked="" type="checkbox"/> X	Unsatisfactory
Date	5/13/2016	Inspector	Joanna Terrigno



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT:	Horseheads Hotel Village of Horseheads Municipal Construction Inspection May 13, 2016
BY:	Jessica Verrigni CPESC, CPSWQ



Concrete washout needs to be maintained.



All catch basins require the correct erosion and sediment control protection.



All silt fence needs to be replaced.



Stormwater forebay of basin.