

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



Project Name LECOM	Date 5-16-2019
Location College Ave, City of Elmira	Permit # NYR11 C547
Weather Conditions sunny, warm	Entry Time: 11:31 am
On-Site Representative Present: None available @ field office	Exit Time: 11:43 am

Construction Site Notes:

-stormwater system is completed
-Work moves forward on building.

Yes	No	N/A	
X			All erosion and sediment control measures installed/constructed
	X		All erosion and sediment control measures maintained properly
	X		Are there currently more than 5 acres disturbed w/o prior approval
	X		Have stabilization measures been initiated in inactive areas
X			Are permanent stormwater control measures being implemented
	X		Was there a discharge into the receiving water on the day of inspection
	X		Evidence of turbidity or oil in the receiving waters
X			Are weekly inspections being performed?
X			Are the inspections being performed by a qualified individual?

Corrections Needed:

-Concrete washout area requires maintenance. Plastic is no longer functioning and wash water is all over the ground surrounding the area. **This issue has been mentioned a number of times on Qualified inspection reports.**

-2nd construction entrance onto Clinton Street requires maintenance.

-Water quality unit that is part of the underground stormwater system is surrounded by the mortar mixing facility and materials. There is no lid on the unit. It only has a broken pallet and safety code on top of it. Mortar material could easily get into the unit and people could potentially dump materials down into it. This unit must be protected during construction especially from materials such as concrete and mortar.

Satisfactory

Marginal

Unsatisfactory XX

5/16/19

Justina Verrigno



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT: LECOM
City of Elmira
Municipal Construction Insp
May 16, 2019

BY: Jessica Verrigni, CPESC, CPSWQ



Concrete washout requires immediate maintenance.



Concrete wash water all over the area surrounding the concrete washout.



Water quality unit that is part of the underground stormwater facility is surrounded by mortar mixing materials. SEE INSPECTION NOTES



2nd Construction entrance requires maintenance.