Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control

Project Name NYSEG Substation Transmission Project	**Date** 11-20-2020
Location Watercure Hill Elmira (T), NY	**Permit #NYR11F644**
Weather Conditions sunny	**Entry Time:**
On-Site Representative Present: none	**Exit Time:**

Construction Site Notes:

-Inspection to verify 80% stabilization has been achieved and it has.

Yes	No	N/A		
		x	All erosion and sediment control measures installed/constructed	
		x	All erosion and sediment control measures maintained properly	
		x	Are there currently more than 5 acres disturbed w/o prior approval	
x			Have stabilization measures been initiated in inactive areas	
	x		Are permanent stormwater control measures being implemented	
	x		Was there a discharge into the receiving water on the day of inspection	
	x		Evidence of turbidity or oil in the receiving waters	
x			Are weekly inspections being performed?	
x			Are the inspections being performed by a qualified individual?	

Corrections Needed:

Satisfactory X Marginal Unsatisfactory

Date 11/20/20	**Inspector** Jessica Vernegra

COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT:	NYSEG Substation Line relocation Town of Elmira Municipal Inspection November 20, 2020
BY:	Jessica Verrigni, CPESC, CPSWQ