

Website Updated:   
 Active Construction List Updated:

Chemung County Stormwater  
 Construction Inspection  
 Erosion and Sediment Control



Project Name	Wellsburg Fire Department	Date	
Location	Main St, Wellsburg	Permit #	NYR11A891
Weather Conditions	partly sunny	Entry Time:	10:47
On-Site Representative Present:	Edger	Exit Time:	11:00

Construction Site Notes:

- contractor finishing up topsoiling out front.
- all areas seeded and growing grass.
- roof drains connected to stormwater system.
- stormwater basin constructed.
- drainage swale along south end of project has been constructed.

Yes	No	N/A	
X			All erosion and sediment control measures installed/constructed
X			All erosion and sediment control measures maintained properly
	X		Are there currently more than 5 acres disturbed w/o prior approval
X			Have stabilization measures been initiated in inactive areas
X			Are permanent stormwater control measures being implemented
	X		Was there a discharge into the receiving water on the day of inspection
	X		Evidence of turbidity or oil in the receiving waters
			Are weekly inspections being performed?
			Are the inspections being performed by a qualified individual?

Corrections Needed:

Satisfactory	X	Marginal	Unsatisfactory
Date	6/1/17	Inspector	Jessica Verrigni



COUNTY OF CHEMUNG  
Chemung County Stormwater Coalition  
851 Chemung Street  
Horseheads, New York 14825  
Ph. 607.796.2216

**PROJECT:** Wellsburg Fire Department  
Village of Wellsburg  
Municipal Inspection  
June 1, 2016

**BY:** Jessica Verrigni, CPESC, CPSWQ



Stormwater channel on the south end of property has been installed and stabilized.



Erosion control blankets have been installed and vegetation is growing.



Roof drains have been tied into the stormwater system.



Conveyance ditch has minor erosion.