

Website Updated:
 Active Construction List Updated

Chemung County Stormwater
 Construction Inspection
 Erosion and Sediment Control



Project Name	Wellsburg Fire Department	Date	6-26-17
Location	Main St, Wellsburg	Permit #	NYR11A891
Weather Conditions	partly cloudy	Entry Time:	11:10 A
On-Site Representative Present:		Exit Time:	11:25 A

Construction Site Notes:

	-All grading work is completed.
	-site nearly ready for close out

Yes	No	N/A	
			All erosion and sediment control measures installed/constructed
			All erosion and sediment control measures maintained properly
			Are there currently more than 5 acres disturbed w/o prior approval
			Have stabilization measures been initiated in inactive areas
			Are permanent stormwater control measures being implemented
			Was there a discharge into the receiving water on the day of inspection
			Evidence of turbidity or oil in the receiving waters
			Are weekly inspections being performed?
			Are the inspections being performed by a qualified individual?

Corrections Needed:

	-no issues.

Satisfactory	<input checked="" type="checkbox"/>	Marginal	<input type="checkbox"/>	Unsatisfactory	<input type="checkbox"/>
Date	6/26/17	Inspector	Jessica Vernigni		



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT: Wellsburg Fire Department
Village of Wellsburg
Municipal Inspection
June 26, 2017

BY: Jessica Verrigni, CPESC, CPSWQ



Swale along front of fire department.



Slopes are well vegetated.



Swale running on south side of parking lot.



Swale intercepting runoff from Berwick Turnpike.



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT: Wellsburg Fire Department
Village of Wellsburg
Municipal Inspection
June 26, 2017

BY: Jessica Verrigni, CPESC, CPSWQ



Reinforced slope protection installed.



Stormwater Basin



Slopes along Bentley Creek stabilized.

