



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT: Villa's at Gardner Road
Village of Horseheads
Municipal Construction Inspection
March 28, 2019

BY: Jessica Verrigni, CPESC, CPSWQ



CB 3- erosion occurring off side slope. Straw bale is causing more erosion issues.



Close up of erosion next to CB 3.



Silt fence around entire property requires repair and replacement.



Silt fence with holes from age. Many areas will need to be replaced.



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT: Villa's at Gardner Road
Village of Horseheads
Municipal Construction Inspection
March 28, 2019

BY: Jessica Verrigni, CPESC, CPSWQ




Major erosion from ditch into stormwater basin.



Rock outlet protection has not been installed.



CB 7 drop inlet protection requires repair.



CB 2 drop inlet protection requires repair.