

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



Project Name Villa's at Gardner Road	Date 5-18-20
Location Lynhurst Ave Horseheads (V), NY	Permit # NYR11P662
Weather Conditions Overcast	Entry Time: 1:38 pm
On-Site Representative Present:	Exit Time: 1:47 pm

Construction Site Notes:

-No work is happening on the site at this time

Yes	No	N/A	
X			All erosion and sediment control measures installed/constructed
	X		All erosion and sediment control measures maintained properly
	X		Are there currently more than 5 acres disturbed w/o prior approval
X	X		Have stabilization measures been initiated in inactive areas
X			Are permanent stormwater control measures being implemented
	X		Was there a discharge into the receiving water on the day of inspection
	X		Evidence of turbidity or oil in the receiving waters
X			Are weekly inspections being performed?
X			Are the inspections being performed by a qualified individual?

Corrections Needed:

-Soil stabilization is needed on all bare soil. There are many areas that have been stabilized but there is more needed. I have circled the locations in red on my photos. When soil is properly protected it should not move all over the site.

-Silt fence needs repair on sections falling down and silt fence needs to be added to the rear of lot one to prevent sediment from leaving the lot.

Satisfactory Marginal X Unsatisfactory

Date 5/18/20 **Inspector** *Jessica Verrietti*



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT: Villa's at Gardener Road
Village of Horseheads
Municipal Inspection
May 18, 2020

BY: Jessica Verrigni, CPESC, CPSWQ



Bare soil requires stabilization.



Bare soil requires stabilization.



Bare soil requires stabilization. Silt fence should extend further in this area so that sediment does not leave lot.

