



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT: Villa's at Gardner Road
Village of Horseheads
Municipal Construction Insp.
April 27, 2021

BY: Jessica Verrigni, CPESC, CPSWQ



Mud tracked all over the road. Parking along road is disrupting drainage to infrastructure.



Driveway constructed around existing catch basin. Catch basin has no sediment control practice to prevent sediment from getting into system.



Work occurring outside of the current lot under construction.



Equipment partially parked in stormwater drainage channel.



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT: Villa's at Gardner Road
Village of Horseheads
Municipal Construction Insp.
April 27, 2021

BY: Jessica Verrigni, CPESC, CPSWQ



Silt fence has been placed in drainage swale and needs to be removed. Silt fence is a barrier to water and will eventually cause erosion issues.



Tree has fallen in permanent stormwater drainage swale. Tree needs to be removed before it causes an erosion issue.



Silt fence crosses permanent stormwater drainage swale. Silt fence needs to be removed from this area.



Slope behind lots 7,8 & 9 has never been repaired and is actively eroding. This issue requires immediate attention.