



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT: Villa's at Gardner Road
Village of Horseheads
Municipal Construction Inspection
June 24, 2019

BY: Jessica Verrigni, CPESC, CPSWQ



Drainage swale along the perimeter of property.



Silt fence has reached its lifespan and requires replacement.



Headcutting is still occurring at the discharge outlet of the drainage swale. Sediment is depositing into the pond.



Rock outlet protection has not been installed.



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT: Villa's at Gardner Road
Village of Horseheads
Municipal Construction Inspection
June 24, 2019

BY: Jessica Verrigni, CPESC, CPSWQ



Sediment eroded into the pond will need to be excavated when the entire project is finished or when 50% capacity is filled with sediment.



Exposed soil needs to be stabilized.



Erosion is still occurring around CB-3. Also, yard waste is in the eroded area now.

