

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



| | |
|----------------------------------------------|----------------------------|
| Project Name Villa's at Gardner Road | Date 12/16/2021 |
| Location Lynhurst Ave. Horseheads (V) | Permit # NYR11A108 |
| Weather Conditions sunny, cool | Entry Time: 8:57 am |
| On-Site Representative Present: none | Exit Time: 9:05 am |

Construction Site Notes:

| |
|-------------------------------------------|
| |
| |
| -No lots are currently under construction |
| |
| |
| |
| |
| |
| |
| |
| |

| Yes | No | N/A | |
|-----|----|-----|-------------------------------------------------------------------------|
| | | x | All erosion and sediment control measures installed/constructed |
| | | x | All erosion and sediment control measures maintained properly |
| | x | | Are there currently more than 5 acres disturbed w/o prior approval |
| x | | | Have stabilization measures been initiated in inactive areas |
| x | | | Are permanent stormwater control measures being implemented |
| | x | | Was there a discharge into the receiving water on the day of inspection |
| | x | | Evidence of turbidity or oil in the receiving waters |
| x | | | Are weekly inspections being performed? |
| x | | | Are the inspections being performed by a qualified individual? |

Corrections Needed:

| |
|--------------------------------------------------------------------------------------|
| -Remove silt fence between lot 6 & 4. Silt fence is off stakes and cannot be reused. |
| -Remove silt fence from drainage swale. |
| -Remove tree from drainage swale. |
| |


Satisfactory x Marginal Unsatisfactory

| | |
|----------------------|-----------------------------------|
| Date 12/16/21 | Inspector Jessica Verrigni |
|----------------------|-----------------------------------|



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

| | |
|-----------------|--------------------------------------------------------------------------------------------|
| PROJECT: | Villa's Village of Horseheads Municipal Construction Inspection December 16, 2021 |
| BY: | Jessica Verrigni, CPESC, CPSWQ |



Silt fence and stakes can be removed. It is not needed until land is open and cannot be reused.



Tree across drainage swale needs to be removed.



Silt fence across drainage swale needs to be removed.



Lot 6 & 7 have been driven over and soil compacted. This are will need to eventually be decompacted.