

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



Project Name Six67 College Ave (Elmira Apartments)	Date 5-20-20
Location College Ave. Elmira, NY	Permit # NYR11G564
Weather Conditions sunny	Entry Time: 9:30
On-Site Representative Present: Kim Boyd, BME, Daniel Kenney, BME	Exit Time:

Construction Site Notes:

	-Construction work has just started. Contractor currently working on demolition and filling in basements.

Yes	No	N/A		
X			All erosion and sediment control measures installed/constructed	
		X	All erosion and sediment control measures maintained properly	
	X		Are there currently more than 5 acres disturbed w/o prior approval	
		X	Have stabilization measures been initiated in inactive areas	
X			Are permanent stormwater control measures being implemented	
	X		Was there a discharge into the receiving water on the day of inspection	
	X		Evidence of turbidity or oil in the receiving waters	
X			Are weekly inspections being performed?	
X			Are the inspections being performed by a qualified individual?	

Corrections Needed:

-NO CORRECTIONS REQUIRED AT THIS TIME.

Satisfactory Marginal Unsatisfactory

Date 5-20-20	Inspector <i>Jessica Verrugni</i>
---------------------	--