

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



Project Name Six67 Apartments	Date 4/27/2021
Location College Ave Elmira, NY	Permit # NYR11G564
Weather Conditions sunny, cool	Entry Time: 9:56 am
On-Site Representative Present: T. Fargo, Reidman	Exit Time: 10:14 am

Construction Site Notes:

-Main work is occurring on the building.
-Stormwater drainage at the front of building under construction.

Yes	No	N/A		
X			All erosion and sediment control measures installed/constructed	
	X		All erosion and sediment control measures maintained properly	
	X		Are there currently more than 5 acres disturbed w/o prior approval	
		X	Have stabilization measures been initiated in inactive areas	
X			Are permanent stormwater control measures being implemented	
	X		Was there a discharge into the receiving water on the day of inspection	
	X		Evidence of turbidity or oil in the receiving waters	
X			Are weekly inspections being performed?	
X			Are the inspections being performed by a qualified individual?	

Corrections Needed:

-Silt sock along W. Fifth Street requires maintenance. There is a spot where asphalt is propping it up off the ground.
-Construction entrance is in good condition but a fair amount of silt has been tracked onto College Ave along curb line (car width). This sediment needs to be swept up the length of the street as soon as practical.

Satisfactory	Marginal	X	Unsatisfactory
Date 4/27/21	Inspector <i>Jessica Verrigno</i>		



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT: Six67 Apartments
City of Elmira
Municipal Construction Insp.
April 27, 2021

BY: Jessica Verrigni, CPESC, CPSWQ



Construction entrance is in good shape but there is a lot of silt in the road. This needs to be cleaned up.

Area along W. Fifth Street.



Silt sock propped up with a piece of asphalt.

Drainage installation around the front of building.