

**Chemung County Stormwater  
Construction Inspection  
Erosion and Sediment Control**



<b>Project Name</b> CDS Monarch	<b>Date</b> 7-18-19
<b>Location</b> Maple Ave Elmira, NY	<b>Permit #</b>
<b>Weather Conditions</b> humid, overcast	<b>Entry Time:</b> 9:00 am
<b>On-Site Representative Present:</b> Justin Bronson- Christa Construction, Dan Yanosh-HUNT	<b>Exit Time:</b>

Construction Site Notes:

-All items have been addressed that were listed on the letter from City of Elmira Dated 1/14/19

Yes	No	N/A	
		x	All erosion and sediment control measures installed/constructed
		x	All erosion and sediment control measures maintained properly
	x		Are there currently more than 5 acres disturbed w/o prior approval
x			Have stabilization measures been initiated in inactive areas
x			Are permanent stormwater control measures being implemented
	x		Was there a discharge into the receiving water on the day of inspection
	x		Evidence of turbidity or oil in the receiving waters
		xx	Are weekly inspections being performed?
			Are the inspections being performed by a qualified individual?

Corrections Needed:

-Maintain seed and mulch around drainage catch basins after rainfall events to ensure proper vegetation is established.

Satisfactory                          Marginal                      Unsatisfactory

<b>Date</b> 7/18/19	<b>Inspector</b> <i>Jessica Corrigan</i>
---------------------	--



COUNTY OF CHEMUNG  
Chemung County Stormwater Coalition  
851 Chemung Street  
Horseheads, New York 14825  
Ph. 607.796.2216

PROJECT: CDS Monarch Senior Living  
Maple Ave  
City of Elmira  
July 18, 2019

BY: Jessica Verrigni, CPESC, CPSWQ



Rock added to the areas that had runoff and erosion issues.



Stone berms have been repaired.



Grading around catch basins have been corrected.



Catch basin is receiving a lot of runoff has washed seed and mulch. The straw and seed will have to be re-done.