

**Chemung County Stormwater  
Construction Inspection  
Erosion and Sediment Control**





<b>Project Name</b> Barrington West Lot 86			<b>Date</b> 3-18-2020
<b>Location</b> Wexton Court, Horeseheads (T), NY			<b>Permit #</b> NYR11F212
<b>Weather Conditions</b> sunny, mild			<b>Entry Time:</b> 1:43 pm
<b>On-Site Representative Present:</b> none			<b>Exit Time:</b> 1:55 pm
Construction Site Notes:			
-No work is happening on this lot at this time. All disturbed areas have been temporarily stabilized.			
Yes	No	N/A	
X			All erosion and sediment control measures installed/constructed
X			All erosion and sediment control measures maintained properly
	X		Are there currently more than 5 acres disturbed w/o prior approval
X			Have stabilization measures been initiated in inactive areas
		X	Are permanent stormwater control measures being implemented
	X		Was there a discharge into the receiving water on the day of inspection
	X		Evidence of turbidity or oil in the receiving waters
X			Are weekly inspections being performed?
X			Are the inspections being performed by a qualified individual?
Corrections Needed:			
NONE			
Satisfactory		XX	Marginal
Date 3-18-2020		Inspector <i>Jessica Verrigni</i>	



**COUNTY OF CHEMUNG**  
**Chemung County Stormwater Coalition**  
**851 Chemung Street**  
**Horseheads, New York 14825**  
**Ph. 607.796.2216**

<b>PROJECT:</b>	Barrington West Lot 86
	Town of Horseheads
	Municipal Inspection
	March 18, 2020
<b>BY:</b>	Jessica Verrigni, CPESC, CPSWQ



Trash is contained but hopefully this is only until a dumpster arrives.