

**Chemung County Stormwater  
Construction Inspection  
Erosion and Sediment Control**



<b>Project Name</b> Barrington West Lot 86	<b>Date</b> 7-15-2020
<b>Location</b> Wexford Ct Horseheads, NY	<b>Permit #</b> NYR11A108
<b>Weather Conditions</b> sunny	<b>Entry Time:</b> 9:55 am
<b>On-Site Representative Present:</b> Brad Kapral	<b>Exit Time:</b> 10:05 am

Construction Site Notes:			
			-Lot 86 is under construction.

Yes	No	N/A		
X			All erosion and sediment control measures installed/constructed	
X			All erosion and sediment control measures maintained properly	
X			Are there currently more than 5 acres disturbed w/o prior approval	
X			Have stabilization measures been initiated in inactive areas	
X			Are permanent stormwater control measures being implemented	
	X		Was there a discharge into the receiving water on the day of inspection	
	X		Evidence of turbidity or oil in the receiving waters	
X			Are weekly inspections being performed?	
X			Are the inspections being performed by a qualified individual?	

Corrections Needed:			
			-No issues at this time

Satisfactory    X                      Marginal                      Unsatisfactory

**Date** 7-15-20      **Inspector** *Gyssa Vercigni*



COUNTY OF CHEMUNG  
Chemung County Stormwater Coalition  
851 Chemung Street  
Horseheads, New York 14825  
Ph. 607.796.2216

<b>PROJECT:</b>	Barrington West
	Town of Horseheads
	Municipal Inspection
	July 15, 2020
<b>BY:</b>	Jessica Verrigni, CPESC, CPSWQ



Lot 85 is now stabilized.



Lot 86 is under construction.



Area where stormwater goes onto school property and pools.



Erosion controls are in place and functioning.