

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



Project Name Byrne Dairy	Date 8-7-2019
Location Corning Road, Town of Horseheads	Permit # NYR11E733
Weather Conditions overcast, humid	Entry Time: 8:51 am
On-Site Representative Present: None	Exit Time: 9:02 am

Construction Site Notes:

-Site work is complete. Awaiting 80% vegetation over the entire property.

Yes	No	N/A		
		x	All erosion and sediment control measures installed/constructed	
		x	All erosion and sediment control measures maintained properly	
	x		Are there currently more than 5 acres disturbed w/o prior approval	
x			Have stabilization measures been initiated in inactive areas	
x			Are permanent stormwater control measures being implemented	
	x		Was there a discharge into the receiving water on the day of inspection	
	x		Evidence of turbidity or oil in the receiving waters	
			Are weekly inspections being performed?	monthly
			Are the inspections being performed by a qualified individual?	

Corrections Needed:

Satisfactory Marginal Unsatisfactory

Date	Inspector
-------------	------------------



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT:	Byrne Dairy
	Town of Horseheads
	Municipal Inspection
	August 7, 2019
BY:	Jessica Verrigni, CPESC, CPSWQ



Status of vegetation at front of the property.



Status of vegetation at side yard.



Status of vegetation on backside of property.



This is the drainage swale on the back side of the property. The slope on the left should be monitored. It looks like erosion could occur.