

**Chemung County Stormwater  
Construction Inspection  
Erosion and Sediment Control**



<b>Project Name</b> Fairport Ridge	<b>Date</b> 6-24-19
<b>Location</b> Prospect Hill Horseheads, NY	<b>Permit #</b> NYR11B689
<b>Weather Conditions</b> sunny clear	<b>Entry Time:</b> 9:52 am
<b>On-Site Representative Present:</b> Scott Mosso	<b>Exit Time:</b> 10:23 am

Construction Site Notes:

-Construction continues on buildings inside and out.
-Road has been rough graded in.
-New construction entrance installed to divert traffic around homes that have residents.
-New septic system being designed closer to the stormwater basin than the other designed/failed system.
Spoke with Jody Allen about setbacks from the stormwater basin. She said that the standard is 50 feet and they are well over 70 feet away.
-Asked Scott about soil restoration and he said they will use the ripper on the John Deere to decompact the soil before putting the topsoil back down.

Yes	No	N/A		
x			All erosion and sediment control measures installed/constructed	
x			All erosion and sediment control measures maintained properly	
	x		Are there currently more than 5 acres disturbed w/o prior approval	
x			Have stabilization measures been initiated in inactive areas	
x			Are permanent stormwater control measures being implemented	
	x		Was there a discharge into the receiving water on the day of inspection	
	x		Evidence of turbidity or oil in the receiving waters	
x			Are weekly inspections being performed?	
x			Are the inspections being performed by a qualified individual?	

Corrections Needed:

- Roof drain outlets are causing minor erosion. Outlet protection will be installed.
- Continue to seed down areas remaining idle.

Satisfactory                      **x**                      Marginal                                      Unsatisfactory

Date 6/24/19                      Inspector Jessica Verrignie



COUNTY OF CHEMUNG  
Chemung County Stormwater Coalition  
851 Chemung Street  
Horseheads, New York 14825  
Ph. 607.796.2216

PROJECT: Fairport Ridge  
Town of Horseheads  
Municipal Construction Inspection  
June 24, 2019


BY: Jessica Verrigni, CPESC, CPSWQ



New construction entrance has been installed.



Graded areas have been temporarily stabilized.



Roof drain outlets are causing minor erosion. Owner will install outlet protection.

