

**Chemung County Stormwater  
Construction Inspection  
Erosion and Sediment Control**



<b>Project Name</b> Fairport Ridge	<b>Date</b> 8-26-2019
<b>Location</b> Prospect Hill Road Horseheads (T), NY	<b>Permit #</b> NYR11B689
<b>Weather Conditions</b> sunny, cool	<b>Entry Time:</b> 10:47 am
<b>On-Site Representative Present:</b> Scott Mosso-owner	<b>Exit Time:</b> 11:27 am

Construction Site Notes:

-Grading of stormwater basin occurring.
-Topsoil and seed/mulch being applied to some front yards.

Yes	No	N/A		
X			All erosion and sediment control measures installed/constructed	
X			All erosion and sediment control measures maintained properly	
	X		Are there currently more than 5 acres disturbed w/o prior approval	
X			Have stabilization measures been initiated in inactive areas	
X			Are permanent stormwater control measures being implemented	
	X		Was there a discharge into the receiving water on the day of inspection	
	X		Evidence of turbidity or oil in the receiving waters	
X			Are weekly inspections being performed?	
X			Are the inspections being performed by a qualified individual?	

Corrections Needed:

-No issues at this time


Satisfactory                          Marginal                      Unsatisfactory

<b>Date</b>	<b>Inspector</b>
-------------	------------------



COUNTY OF CHEMUNG  
Chemung County Stormwater Coalition  
851 Chemung Street  
Horseheads, New York 14825  
Ph. 607.796.2216

**PROJECT:** Fairport Ridge  
Town of Horseheads  
Municipal Inspection  
August 26, 2019

**BY:** Jessica Verrigni, CPESC, CPSWQ




Construction entrance/road in good condition.



Topsoil piles actively being utilized.



Stormwater basin under construction.



Crews topsoiling and stabilizing front yards.