

Chemung County Department of Health
Environmental Health Services
103 Washington Street
P. O. Box 588
Elmira, NY 14902-0588
(607) 737-2019
EHS@chemungcountyny.gov

Campground Inspection Summary Report

Operation: PARK STATION RECREATION CENTER (ID: 265015)
Facility Name: PARK STATION RECREATION CENTER
Facility Code: 07-2437 Facility Email: Isprague1@chemungcountyny.gov
Facility Address: 2 West Beaver Pond Road, Erin, NY 14838

To the Attention of:

Don Bishop
COUNTY OF CHEMUNG
Buildings & Grounds (d. Bishop)
217 Madison Ave. (interdept)
Elmira, NY 14901
Email: dbishop@chemungcountyny.gov

Inspection

Date: July 15, 2021 11:23 AM
Inspector: Zachary Brueckman (zbrueckman@chemungcountyny.gov)
Responsible Person: Emailed To Operator

Summary

| | |
|--|---|
| Number of Public Health Hazards Found: | 0 |
| Number of Public Health Hazards NOT Corrected: | 0 |
| Number of Other Violations Found: | 2 |

Each item found in violation is reported below along with the code requirement.

NO PUBLIC HEALTH HAZARDS REPORTED

GENERAL

ITEM #22 WAS FOUND IN VIOLATION 1 TIME(S).

All or parts of the item are violations.

Code Requirements: Electrical service; wiring and fixtures installed, maintained {7-3.17}

Inspector Findings: Observed GFI electrical outlet test buttons not operation in the following lots, and were unable to be reset: lots 28, 22, 11, 2. Time table of correction set for 7/22/21

GENERAL

ITEM #24 WAS FOUND IN VIOLATION 1 TIME(S).

All or parts of the item are violations.

Code Requirements: Campsites - adequately sized {7-3.8}

Inspector Findings: On lot 34 observed 1 recreational vehicle parked next to a tent, with less than required 10 feet of separation distance (~3 ft). TTOC set for 7/19/21

Additional Information Collected During Inspection

Comments: Obtained a free chlorine residual reading of 0.8 mg/L in utility sink cold water tap, located at laundry facility. All bathrooms were stocked with warm water, soap, and paper towels. Shower facility was able to produce hot water on demand. All water fountains in campground were observed to have available drinking water for campers.



Inspector: Zachary Brueckman
(zbrueckman@chemungcountyny.gov)