

Campground Inspection Summary Report

Operation: GARDNER HILL CAMPGROUND (ID: 265024)
Facility Name: GARDNER HILL CAMPGROUND
Facility Code: 07-2565 Facility Email: andrew@allsquaredup.com
Facility Address: 1451 Norway Road, Lowman, NY 14861

To the Attention of:

Andrew Dondero
Dba - Gardner Hill Campground
1451 Norway Rd
Lowman, NY 14861
Email: joannejhdondero@yahoo.com

Inspection

Date: August 13, 2020 02:30 PM
Inspector: Leanne Schad (lschad@chemungcountyny.gov)
Responsible Person: Andrew Dondero

Summary

Number of Public Health Hazards Found:	0
Number of Public Health Hazards NOT Corrected:	0
Number of Other Violations Found:	1

Each item found in violation is reported below along with the code requirement.

NO PUBLIC HEALTH HAZARDS REPORTED

SEWAGE FACILITIES

ITEM #48 WAS FOUND IN VIOLATION 1 TIME(S).

All or parts of the item are violations.

Code Requirements: Toilet facilities - adequate, design - maintained {7-3.15(a)}

Inspector Findings: Observed interior wall on divider between toilet and shower to be in disrepair in the men's bathroom in lower bathhouse facility. Wall had been removed and placed off to side exposing plumbing from adjacent toilet stall. A time table of correction has been issued for August 31, 2020.

Additional Information Collected During Inspection

Comments: Observed two portable toilets in upper field within pine trees that are being used as temporary restroom facilities until the new bathhouse is finished. Portable toilet facility was properly equipped with a hand washing sink with warm and cold water, soap and paper towels. Observed the men's and women's bathhouse in lower field area near laundry room, properly stocked and equipped with warm and cold water, paper towels and soap. Observed showers to be properly working and equipped with warm water. Observed a chlorine residual of 3.0 mg/L from hand washing sink in women's bathroom facility. Observed campsites to be properly spaced at least 10ft apart from one another. Observed proper waste receptacles placed throughout campground as to avoid improper placement of refuse.



Inspector: Leanne Schad
(lschad@chemungcountyny.gov)



Received by: Andrew Dondero